



Photo 17: View of engine propeller blades as received at engine inspection facility. All were cut at blade root to facilitate shipping.